




stngco.com

CORPORATE OFFICE

2691 Saturn Street, Brea, CA 92821
Tel: (714) 524-0663, Fax: (714) 364-8113



ST&G CORPORATION
Rm. 911 43, Yangsan-ro
Yeongdeungpo-gu, Seoul, Korea



MDSS GmbH

Schiffgraben 41, 30175 Hannover, Germany



REF: 1221S

3 Prong Rotating Base, SS

Weight: 116 grams
Weight Limit: 136kg / 300lbs
Torque recommendation
Pylon clamp screw – 10 Nm



1221S IFU REV. D (07-12-23)



stngco.com

CORPORATE OFFICE

2691 Saturn Street, Brea, CA 92821
Tel: (714) 524-0663, Fax: (714) 364-8113



ST&G CORPORATION
Rm. 911 43, Yangsan-ro
Yeongdeungpo-gu, Seoul, Korea



MDSS GmbH

Schiffgraben 41, 30175 Hannover, Germany



REF: 1221S

3 Prong Rotating Base, SS

Weight: 116 grams
Weight Limit: 136kg / 300lbs
Torque recommendation
Pylon clamp screw – 10 Nm



1221S IFU REV. D (07-12-23)



stngco.com

CORPORATE OFFICE

2691 Saturn Street, Brea, CA 92821
Tel: (714) 524-0663, Fax: (714) 364-8113



ST&G CORPORATION
Rm. 911 43, Yangsan-ro
Yeongdeungpo-gu, Seoul, Korea



MDSS GmbH

Schiffgraben 41, 30175 Hannover, Germany



REF: 1221S

3 Prong Rotating Base, SS

Weight: 116 grams
Weight Limit: 136kg / 300lbs
Torque recommendation
Pylon clamp screw – 10 Nm



1221S IFU REV. D (07-12-23)




stngco.com

CORPORATE OFFICE

2691 Saturn Street, Brea, CA 92821
Tel: (714) 524-0663, Fax: (714) 364-8113



ST&G CORPORATION
Rm. 911 43, Yangsan-ro
Yeongdeungpo-gu, Seoul, Korea



MDSS GmbH

Schiffgraben 41, 30175 Hannover, Germany



REF: 1221S

3 Prong Rotating Base, SS

Weight: 116 grams
Weight Limit: 136kg / 300lbs
Torque recommendation
Pylon clamp screw – 10 Nm



1221S IFU REV. D (07-12-23)

1. Application

The 1221S, 3 Prong Rotating Base, SS is to be exclusively used for the prosthetic fitting of lower

2. Description

The 3 Prong Rotating Base, SS is integrated into the prosthetic socket's laminate as lamination anchor. This rotating adapter can be screwed into a thermoplastic test socket for the trial fitting of transibial or transfemoral amputees. By engaging the threads from these products, 1215S/T, 1216S/T, 1225S/T, 1704T or 1725T, to 3 Prong Rotating base, adjust the desired alignment and tighten the clamp cap screw to recommended torque. The four set screws are used for anchoring the part to the mating pyramid system as well as for making angular adjustment for alignment. The modular connection can be removed from the lamination anchor by removing the clamp cap screw. This connection functions as a rotation adjustment. Apply locate to all screws once the alignment and connection is finalized.

3. Reinforcement Recommendations

The type of reinforcement used depends on the type of loading expected. It generally consists of four to six layers of Nyglass, some carbon reinforcement and 1-1/2 layers of fiberglass stockinette

4. Warranty

Warranty applies only when the product is used as intended without modification, following all manufacturer's recommendations. ST&G offers 2 years warranty.

5. Declaration of Conformity

ST&G as manufacturer declares that the 1221S, 3 Prong Rotating Base, SS conforms to the requirements of Council EU 2017/745 (MDR).

ST&G products are manufactured and tested for a particular weight and activity impact level. Use by another user for whom it was not originally intended may cause injury and voids any written warranty, or liability. The liability shall fall upon those that resale/provide the product to anyone other than the original user delivered to. Not



Notice

Tighten all the screws, which are side by side, using the torque wrench.

3

2

1. Application

The 1221S, 3 Prong Rotating Base, SS is to be exclusively used for the prosthetic fitting of lower extremity amputations.

2. Description

The 3 Prong Rotating Base, SS is integrated into the prosthetic socket's laminate as lamination anchor. This rotating adapter can be screwed into a thermoplastic test socket for the trial fitting of transibial or transfemoral amputees. By engaging the threads from these products, 1215S/T, 1216S/T, 1225S/T, 1704T or 1725T, to 3 Prong Rotating base, adjust the desired alignment and tighten the clamp cap screw to recommended torque. The four set screws are used for anchoring the part to the mating pyramid system as well as for making angular adjustment for alignment. The modular connection can be removed from the lamination anchor by removing the clamp cap screw. This connection functions as a rotation adjustment. Apply locate to all screws once the alignment and connection is finalized.

3. Reinforcement Recommendations

The type of reinforcement used depends on the type of loading expected. It generally consists of four to six layers of Nyglass, some carbon reinforcement and 1-1/2 layers of fiberglass stockinette

4. Warranty

Warranty applies only when the product is used as intended without modification, following all manufacturer's recommendations. ST&G offers 2 years warranty.

5. Declaration of Conformity

ST&G as manufacturer declares that the 1221S, 3 Prong Rotating Base, SS conforms to the requirements of Council EU 2017/745 (MDR).

ST&G products are manufactured and tested for a particular weight and activity impact level. Use by another user for whom it was not originally intended may cause injury and voids any written warranty, or liability. The liability shall fall upon those that resale/provide the product to anyone other than the original user delivered to. Not



Notice

Tighten all the screws, which are side by side, using the torque wrench.

3

2

1. Application

The 1221S, 3 Prong Rotating Base, SS is to be exclusively used for the prosthetic fitting of lower

2. Description

The 3 Prong Rotating Base, SS is integrated into the prosthetic socket's laminate as lamination anchor. This rotating adapter can be screwed into a thermoplastic test socket for the trial fitting of transibial or transfemoral amputees. By engaging the threads from these products, 1215S/T, 1216S/T, 1225S/T, 1704T or 1725T, to 3 Prong Rotating base, adjust the desired alignment and tighten the clamp cap screw to recommended torque. The four set screws are used for anchoring the part to the mating pyramid system as well as for making angular adjustment for alignment. The modular connection can be removed from the lamination anchor by removing the clamp cap screw. This connection functions as a rotation adjustment. Apply locate to all screws once the alignment and connection is finalized.

3. Reinforcement Recommendations

The type of reinforcement used depends on the type of loading expected. It generally consists of four to six layers of Nyglass, some carbon reinforcement and 1-1/2 layers of fiberglass stockinette

4. Warranty

Warranty applies only when the product is used as intended without modification, following all manufacturer's recommendations. ST&G offers 2 years warranty.

5. Declaration of Conformity

ST&G as manufacturer declares that the 1221S, 3 Prong Rotating Base, SS conforms to the requirements of Council EU 2017/745 (MDR).

ST&G products are manufactured and tested for a particular weight and activity impact level. Use by another user for whom it was not originally intended may cause injury and voids any written warranty, or liability. The liability shall fall upon those that resale/provide the product to anyone other than the original user delivered to. Not



Notice

Tighten all the screws, which are side by side, using the torque wrench.

3

2

1. Application

The 1221S, 3 Prong Rotating Base, SS is to be exclusively used for the prosthetic fitting of lower extremity amputations.

2. Description

The 3 Prong Rotating Base, SS is integrated into the prosthetic socket's laminate as lamination anchor. This rotating adapter can be screwed into a thermoplastic test socket for the trial fitting of transibial or transfemoral amputees. By engaging the threads from these products, 1215S/T, 1216S/T, 1225S/T, 1704T or 1725T, to 3 Prong Rotating base, adjust the desired alignment and tighten the clamp cap screw to recommended torque. The four set screws are used for anchoring the part to the mating pyramid system as well as for making angular adjustment for alignment. The modular connection can be removed from the lamination anchor by removing the clamp cap screw. This connection functions as a rotation adjustment. Apply locate to all screws once the alignment and connection is finalized.

3. Reinforcement Recommendations

The type of reinforcement used depends on the type of loading expected. It generally consists of four to six layers of Nyglass, some carbon reinforcement and 1-1/2 layers of fiberglass stockinette

4. Warranty

Warranty applies only when the product is used as intended without modification, following all manufacturer's recommendations. ST&G offers 2 years warranty.

5. Declaration of Conformity

ST&G as manufacturer declares that the 1221S, 3 Prong Rotating Base, SS conforms to the requirements of Council EU 2017/745 (MDR).

ST&G products are manufactured and tested for a particular weight and activity impact level. Use by another user for whom it was not originally intended may cause injury and voids any written warranty, or liability. The liability shall fall upon those that resale/provide the product to anyone other than the original user delivered to. Not



Notice

Tighten all the screws, which are side by side, using the torque wrench.

3

2

1. Application

The 1221S, 3 Prong Rotating Base, SS is to be exclusively used for the prosthetic fitting of lower extremity amputations.

2. Description

The 3 Prong Rotating Base, SS is integrated into the prosthetic socket's laminate as lamination anchor. This rotating adapter can be screwed into a thermoplastic test socket for the trial fitting of transibial or transfemoral amputees. By engaging the threads from these products, 1215S/T, 1216S/T, 1225S/T, 1704T or 1725T, to 3 Prong Rotating base, adjust the desired alignment and tighten the clamp cap screw to recommended torque. The four set screws are used for anchoring the part to the mating pyramid system as well as for making angular adjustment for alignment. The modular connection can be removed from the lamination anchor by removing the clamp cap screw. This connection functions as a rotation adjustment. Apply locate to all screws once the alignment and connection is finalized.

5. Declaration of Conformity

ST&G as manufacturer declares that the 1221S, 3 Prong Rotating Base, SS conforms to the requirements of Council EU 2017/745 (MDR).

ST&G products are manufactured and tested for a particular weight and activity impact level. Use by another user for whom it was not originally intended may cause injury and voids any written warranty, or liability. The liability shall fall upon those that resale/provide the product to anyone other than the original user delivered to. Not



Notice

Tighten all the screws, which are side by side, using the torque wrench.

3

2

3. Reinforcement Recommendations

The type of reinforcement used depends on the type of loading expected. It generally consists of four to six layers of Nyglass, some carbon reinforcement and 1-1/2 layers of fiberglass stockinette

4. Warranty

Warranty applies only when the product is used as intended without modification, following all manufacturer's recommendations. ST&G offers 2 years warranty.

5. Declaration of Conformity

ST&G as manufacturer declares that the 1221S, 3 Prong Rotating Base, SS conforms to the requirements of Council EU 2017/745 (MDR).

ST&G products are manufactured and tested for a particular weight and activity impact level. Use by another user for whom it was not originally intended may cause injury and voids any written warranty, or liability. The liability shall fall upon those that resale/provide the product to anyone other than the original user delivered to. Not



Notice

Tighten all the screws, which are side by side, using the torque wrench.

3

2